

RICHLAND COUNTY GEODETIC SURVEY MARKER

OHIO NORTH ZONE (3401)

POINT NUMBER: 9006A

R/T/S: 19-20-06 Troy Twp

STATION NAME: 48

TYPE OF MARK: RR Spike

SET BY: County - MC

STAMPING ON MARK:


DATE SET: 1995.

METHOD OF SURVEY: GPS

FILE: 1995 Report, 2003 Report

COORDINATES BY: Geometrics

LOCATION: The station is located in Richland County, Ohio about 5 mile(s) NW of the Village of Lexington. To reach the station from the intersection of S.R. 97 and US 42 in Lexington proceed NW along S.R. 97, 5 mile(s) to its intersection with SR 314. Turn right and proceed north along SR 314, 0.8 mile(s) to its intersection with Blooming Grove Rd. Turn left and proceed West along Blooming Grove Rd, 0.3 mile(s). The station is on the left.



HORIZONTAL DATUM: NAD 83 (86)	HORIZONTAL ORDER: 2nd Class II
LATITUDE: 40 43 02.41059 N	LONGITUDE: 082 40 15.87106 W
SPC NORTH: 382829.930 US ft.	SPC EAST: 1921078.355 US ft.
SPC NORTH: 116686.796 m	SPC EAST: 585545.854 m
VERTICAL DATUM: NAVD88	VERTICAL ORDER: 3rd
ELEVATION (METERS): 410.840	ELEVATION (US FT.): 1347.897
HORIZONTAL DATUM: NAD 83 (95)	HORIZONTAL ORDER: 2nd Class II
LATITUDE: 40 43 02.40721 N	LONGITUDE: 082 40 15.85819 W
SPC NORTH: 382829.586 US ft.	SPC EAST: 1921079.346 US ft.
SPC NORTH: 116686.691 m	SPC EAST: 585546.156 m
COMBINED FACTOR: 0.99989873	
Notes:	

RICHLAND COUNTY CONTROL POINTS

AERIAL VIEW 2005



STATION SKETCH

