

PROPERTY SURVEY
FOR
MOOSE LODGE
SHELBY, RICHLAND COUNTY
OHIO

MOOSE LODGE



Description: Situated in the Township of Sharon, Twp. 22, Range 12, City of Shelby, County of Richland, State of Ohio and being a part of Outlot No. 55 and bounded and described as follows:

Beginning at an iron pipe on the west side of North Gamble Street, State Highway 66, at a point which is the northeast corner of Inlot No. 713; thence west along the north lot line of Inlot No. 713 a distance of 150.0 feet to an iron pipe; thence N 70° 32' W along the property of the Moose Lodge a distance of 109.0 feet to an iron pipe; thence east along the Moose Lodge driveway and parallel to the south line a distance of 150.0 feet to an iron pipe on the west side of North Gamble Street rightaway; thence S 70° 32' E along North Gamble Street rightaway a distance of 109.0 feet to the point of beginning, containing 0.375 acres more or less.

I certify that I have made a survey of the above property and have located iron pipe as indicated.

F. E. Krocka

F. E. Krocka

Reg. Surveyor No. 3702

Dated April 9 1959